U.S. ARMY CORPS OF ENGINEERS US Army Corps of Engineers District: CEMVN LL=47.1 MLLW MOSS LAKE CALCASIEU SHIP CHANNEL UPPER SHEET 8 CR_08_UPR_20241212_CS UPPER 3 08_UPR_ 12 Decem 596,000 2,647,000 NOTES: Horizontal Coordinate System: North American Datum of 1983 (NAD83), projected to the State Plane VICINITY MAP Coordinate System (SPCS), Louisiana South Zone. Distance units in U.S. Survey Feet. **LEGEND** Vertical Datum: -16' and above Gage Reading: DM 102 VRN: -0.09 MLLW AVG. Soundings are shown in feet and indicate depths below Mean Lower Low Water Datum (MLLW). Datum Relationships for gage 73575 as of December 2013:

0.0' NAVD88 (OPUS 2013) = 0.8' MLLW = 1.8' MLG or 0.0' MLLW = 1.0' MLG 3 Fluff Thickness (feet)* CALM -16' to -21' Cable Area Sea Conditions: --- Federal Navigation Channel M/V TECHE -21' to -26' Vessel Name: 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 — Federal Navigation Center Line Placement Area Shoalest Sounding** Distances on the Calcasieu River are shown at 1 mile intervals. Survey Type: CONDITION -26' to -33' Esri, HERE, Garmin, (c) OpenStr the GIS use **- OWER Channel** Sounding Frequency***: LOW The location of navigation aids are base on and provided by the U.S. Coast Guard **Upper Channel** As-built Pipeline/Cable Anchorage Area Beacon, General -33' to -39' and USACE survey crews. -39' to -41' ∅ Obstruction Point ---- Unconfirmed Pipeline/Cable 2022 Aerial Photography data source: PAR LLC Red Navigation Buoy Sheet -41' to -43' Reference is N.O.A.A. Navigation Chart No. 11339. — Project Depth Contour Wrecks-Submerged Reference -43' and below Green Navigation Buoy 1,200 400 * Difference between high and low frequency elevations where greater than 1.0'. Number 8 **of** 53 ** Shoalest Sounding per Quarter per Reach. *** High frequency (200 kHz) survey data represents the first signal return at a sounding location and will include suspended solids, known as "fluff", if present. Low frequency (20 kHz) survey data normally penetrates through this "fluff" layer to depict elevations of consoldiated bottom Revison Number:

material. Low frequency accuracies may vary depending on channel conditions and fathometer

4.2-20200420