U.S. ARMY CORPS OF ENGINEERS 518,000 512,000 US Army Corps of Engineers District: CEMVN RED LIGHTED CAUTION BUOY LL=42.6 MLLW 43 CALCA SEU CHAN LL=43.6 MLLW LL=45.6 MLLW 45.8 SHIP CHANNEI SHEET 2 515,000 518,000 512,000 2,641,000 CALCASIEU NOTES: Horizontal Coordinate System: North American Datum of 1983 (NAD83), projected to the State Plane VICINITY MAP 07 Coordinate System (SPCS), Louisiana South Zone. Distance units in U.S. Survey Feet. **LEGEND** Vertical Datum: -16' and above DM 72 VRN: 1.40 MLLW AVG Gage Reading: Soundings are shown in feet and indicate depths below Mean Lower Low Water Datum (MLLW). Datum Relationships for gage 73615 as of December 2013: 0.0' NAVD88 (2009.55) = 1.1' MLLW = 2.1' MLG or 0.0' MLLW = 1.0' MLG 3 Fluff Thickness (feet)* Sea Conditions: CALM -16' to -21' --- Federal Navigation Channel Cable Area **MV TECHE** Vessel Name: -21' to -26' 9 11 12 13 14 15 16 17 18 19 20 21 — Federal Navigation Center Line Placement Area Shoalest Sounding** Distances on the Calcasieu River are shown at 1 mile intervals. CONDITION Survey Type: -26' to -33' Esri, HERE, Garmin, (c) OpenStre contributors Sounding Frequency***: LOW The location of navigation aids are base on and provided by the U.S. Coast Guard **Upper Channel** As-built Pipeline/Cable Anchorage Area -33' to -39' Beacon, General and USACE survey crews. -39' to -41' ∅ Obstruction Point Unconfirmed Pipeline/Cable 2022 Aerial Photography data source: PAR LLC 40 41 42 43 44 45 46 47 48 49 Red Navigation Buoy Sheet -41' to -43' Reference is N.O.A.A. Navigation Chart No. 11339. Wrecks-Submerged — Project Depth Contour Reference -43' and below Green Navigation Buoy 400 1,200 * Difference between high and low frequency elevations where greater than 1.0'. Number ** Shoalest Sounding per Quarter per Reach. 20 **of** 53 *** High frequency (200 kHz) survey data represents the first signal return at a sounding location and will include suspended solids, known as "fluff", if present. Low frequency (20 kHz) Bar Charnel ERE, Garmin, (c) OpenStreet Wiles contributors, and the GIS user community survey data normally penetrates through this "fluff" layer to depict elevations of consoldiated bottom Revison Number: material. Low frequency accuracies may vary depending on channel conditions and fathometer 4.2-20200420