




Gage Reading: CAMERON VRN: 1.55 MLLW AVG
 Sea Conditions: CHOP
 Vessel Name: MV TECHE
 Survey Type: CONDITION
 Sounding Frequency***: LOW

N
E
S
W

Feet
 0 400 800 1,200 1,600

CALCASIEU SHIP CHANNEL
 BAR SHEET 32
 CR_32_BAR_20250423_CS
 23 April 2025

Submitted: _____	Surveyed By: SPJS
Recommended: Chief, Survey Section	Plotted By: JH
Approved: Chief, Waterways Maintenance Section	Checked By: JH

DISCLAIMER

Access Constraints: The United States Government furnishes these data and the recipient accepts and uses them with the express understanding that the US Government makes no warranties, expressed, or implied concerning the accuracy, completeness, readability, usability or suitability for any particular purpose of the data. The recipient understands that the data are provided "as is" without any liability whatsoever to any person by reason of any use made thereof. These data belong to the Government. Therefore the recipient fully agrees not to represent these data to anyone as other than Government provided data. The recipient may not transfer these data to others without also transferring this Disclaimer.

The information depicted on this map represents the results of a survey conducted on the date indicated and can only be considered to represent the general condition existing at that time.

Data Constraints: Hydrographic survey data is subject to change rapidly due to several factors including but not limited to dredging activity and natural shoaling and scouring processes. The U. S. Army Corps of Engineers accepts no responsibility for changes in the hydrographical conditions which may alter the date of the data. The Corps of Engineers does not guarantee the accuracy of any of the application of the data for other than its intended purpose.



**US Army Corps
of Engineers
District: CEMVN**