





 Gage Reading: DM 119 VRN: 1.33 MLLW AVG.
 Sea Conditions: CALM
 Vessel Name: M/V TECHE
 Survey Type: CONDITION
 Sounding Frequency***: LOW

Feet

 0 400 800 1,200 1,600



**US Army Corps
of Engineers
District: CEMVN**

DISCLAIMER

The United States Government furnishes no warranty, either expressed or implied, regarding the accuracy, reliability, completeness, or timeliness of the information and data furnished herein. The United States makes neither recommendations nor endorsements of products made therein. These claims belong to the Government. Therefore the user assumes all liability for any damage or loss resulting from these data to others without also transferring this Disclaimer.

The information depicted on this map represents the results of a study conducted by the U.S. Army Corps of Engineers to represent the general condition existing at that time.

Distribution Location: The data represents the results of data collection and processing for a specific US Army Corps of Engineers project. This data is available to the public through the Internet. It is only valid for its intended use, consistent, time and accuracy of any of the application of the data for other than its intended purpose.

Data Collection: Hydrographic survey data is subject to change over time due to changes in water levels, sedimentation, erosion activity and natural shoaling and scouring processes. The U.S. Army Corps of Engineers maintains a regular update of the data in publication. This data is intended for U.S. Army Corps of Engineers internal use. Product maintains status as "Army Corps of Engineers Internal Use Only".

U.S. ARMY CORP. OF ENGINEERS	
Submitted _____	Reviewed By: SP, JS _____
Recommended: Chief, Survey Section _____	Plotted By: BD _____
Approved: _____	Checked By: AO/JH _____
Chief, Waterways Maintenance Section	

CALCASIEU SHIP CHANNEL
CLOONEY ISLAND
CR_52_CLI_20250806_CS
06 August 2025

**Sheet
Reference
Number**
52 **of** 53

Revision Number:
5.25.04.03-5.25.04.03